

## **Enforcement Orders Signed October 20, 2015**

**City of Alto,**  
**Docket No. GUD 10392**

System Name: System of CO ID 0005

Rules violated:

**Violation No. 1**

Requirement: Title 16, 8.208(f)

The operator did not have written policies/practices/procedures to identify the location of compression couplings at currently known service riser installations, expose and inspect these couplings, and replace these couplings if they are not manufactured and/or installed in accordance with ASTM D2513 specifications for Category 1 fittings.

Note: TAC 8.208, The operator's O&M manual does not have a procedure for compression couplings that meets the requirements of TAC rule 8.208. Compression coupling reports dating back to 2007 and 2008 are found in operator's records. Beyond those records are letter sent and received from the RRC about compression couplings.

Penalty collected: \$2,500