



Moist area with  
grassy vegetation



Approximate Scale: 1 inch = 40 feet

Legend	
	Steel 55-gallon drum
	Plastic drum
	Fence
	Photo No. & Direction



Site Map with Photo Locations	Former D&G Operating Company Evans Unit 05775 Lease Chambers County Winnie, Texas
March 2005	
Figure 8	<i>CORRIGAN CONSULTING, INC.</i>



**Photograph No. 1 – Former D & G Operating Company, Evans Unit Well #1 Site, Winnie, TX**  
View of fenced area with on-site structures. Facing South (MSH 04/14/04)



**Photograph No. 2 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of fenced area with on-site structures. Facing Southwest (JW 10/07/04)



**Photograph No. 3 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of tool trailer located within fenced area. Facing South (MSH 04/14/04)



**Photograph No. 4 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of an ARS technician collecting samples from inside tool house. Facing Southeast (JW 07/21/04)



**Photograph No. 5 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of trash inside tool house. (JW 07/21/04)



**Photograph No. 6 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of plastic drum lying on its side, within fenced area. Contents unknown. Facing South (MSH 04/14/04)



**Photograph No. 7 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of the close-up of wellhead structure and 55-gallon drums within fenced area. Facing South (MSH 04/14/04)



**Photograph No. 8 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of the steel workover tank in southwest portion of fenced area. Facing Northeast (MSH 04/14/04)



**Photograph No. 9– Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of the steel workover tank inside fenced area. Note corrosion and leaking from tank.  
Facing Northeast (MSH 04/14/04)



**Photograph No. 10 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of corrosion and water leaking from workover tank. Facing North (MSH 04/14/04)



**Photograph No. 11 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of expandable foam insulation used to stop leak from workover tank. Facing North (JW 09/08/04)



**Photograph No. 12 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of wooden cover constructed to prevent additional rainwater from overfilling workover tank.  
The wooden cover was later covered with a tarp. Facing North (JW 09/08/04)



**Photograph No. 13 – Former D & G Operating Company, Evans Unit Well #1, Winnie, TX**  
View of shallow drainage ditch (to left) running along southern boundary of fenced area.  
Facing West (MSH 04/14/04)