

## Enforcement Orders Signed June 4, 2019

**GUD 10776**

### ATMOS ENERGY CORP., MID TEX

System Name: D/FW AIRPORT N & S HP

System ID No.: 612470

**Violation Code: 16E-018-022**

The Operator's Line Locator failed to mark the approximate center line of the underground pipeline(s).

Requirement: Title 16, 18.8 (b)

#### Violation Notes

Evaluation ID	Violation State	Previous Evaluation ID	Location	Note
20171557	Uncorrected		International Parkway Service Rd. at Crossunder No. 1, DFW Airport, Tarrant Co., Texas	Texas Administrative Code Title 16, 18.8 (b) Locators shall mark the approximate center line of an underground pipeline.  A review of the incident site identified that the original line locate markings and the emergency locates performed for the damage repairs were both marking an unidentified deeper utility line and not the Atmos line intended. The Atmos contractor performing line locates on behalf of Atmos failed to properly mark the gas mainline and efforts to pothole and visually identify the mainline failed to properly identify the line marked.

**Penalty collected: \$2,500.00**