

Enforcement Orders Signed August 21, 2018

SOUTHCROSS CCNG TRANSMISSION LTD

Docket No. GUD 10588

System Name:

SR13, 12",15" (System id #551696)

Violations:

Item No	Requirement	Description	Location
1	49 CFR 192.603(b)	Records necessary to administer the operation and maintenance plan were not maintained or were inadequate.	Maintenance activities performed at the Woodsboro Processing Plant
2	49 CFR 199.105 (b)	The operator did not conduct the prescribed post-accident testing for the presence of a prohibited drug.	Operators Employee
3	49 CFR 199.115 (a)	Where the anti-drug program was being provided by contract for employees who are contractors or employees employed by contractors, the operator's actions were not sufficient to ensure that the program was being conducted in accordance with Part 199 and DOT Procedures.	Contract Employees
4	49 CFR 191.15(a)	The operator of a transmission or gathering pipeline system did not submit DOT Form PHMSA F 7100.2 as soon as practicable but not more than 30 days after detection of an incident required to be reported under §191.5 .	Woodsboro Plant Incident

Penalty collected: \$104,000.00