

## Enforcement Orders Signed June 4, 2019

**GUD 10382**

### WTG GAS TRANSMISSION COMPANY

System Name: WTGGT SNYDER, 16"

System ID No.: 962426

**Violation Code: 192-161-002**

The pipeline and its associated equipment at the location(s) below did not have adequate anchors or supports to resist longitudinal forces caused by a bend or offset in the pipe.

Requirement: 49 CFR 192.161(a)(2)

Violation Notes				
Evaluation ID	Violation State	Previous Evaluation ID	Location	Note
20141566	Uncorrected		Snyder Compressor Station, Martin County, Compressor #7 Blow-down vent stack piping.	The vent stack was not designed in a way that secured the 2" threaded steel piping with two each 90 degree bends with adequate anchors or supports. When the piping separated, there were no anchors or supports which held it in place.

**Violation Code: 192-805-010**

Operating personnel was not qualified to perform the given covered task listed in the Operator's OQ program.

Requirement: 49 CFR 192.805 (b)

Violation Notes				
Evaluation ID	Violation State	Previous Evaluation ID	Location	Note
20141566	Uncorrected		Snyder Compressor Station, Compressor Operation and Maintenance.	As he was working on the Snyder Compressor Station, #7 compressor, company affiliate employee Johnny Plasentillo did not hold qualifications under the operator's Operator Qualification program which would have allowed him to perform maintenance upon, or restart/shut down the compressor. Mr. Plasentillo was working unassisted and not under direct supervision of a qualified individual who might have been able to direct his actions or recognize an abnormal operating condition associated with releasing pressure from the compressor unit.

**Penalty collected: \$160,000.00**